



Muskogee County Detention Center







STATEMENT

PRINT NAME Doyle Rowland **DATE** 5/12/26

On May 11 at approximately 7:20 pm, I Detention Officer Rowland, Doyle, was turning onto 71st in Tulsa, when I ran into the back of a vehicle on the off ramp. Supervisor was notified. Administrator was notified. The Under Sheriff was notified. Information was exchanged. Police were notified. End of Report


SIGNATURE



22nd day of June 20 26
Chairman 
Member 
Member 
Attest 
County Clerk

E-MAILED
6/22 11:24

Trident Collision
6335 E 41st St
Tulsa, OK 74135
(918)-439-4444

*** PRELIMINARY ESTIMATE ***

05/12/2026 11:04 AM

Owner

Owner: CARLY TREECE
Address: 7 W 34TH ST
City State Zip: Sand Springs, OK 74063
Email: CARLY@TVLSESTUDIOS.COM

Cell: (918)232-1890
FAX:

Inspection

Inspection Date: 05/12/2026 11:02 AM

Inspection Type:

Company: TRIDENT COLLISION
Contact: ERIN DICKERSON
Address: 6335 EAST 41ST STREET
City State Zip: Tulsa, OK 74135
Email: ERIN@TRIDENTCOLLISION.COM

Appraiser License #2 :

Work/Day:
FAX:

Repairer

Repairer: Trident Collision Repair
Address: 6335 E 41st street
City State Zip: Tulsa, OK 74135

Contact:
(918)439-4444

Target Complete Date/Time:

Days To Repair: 3

Vehicle

2014 Subaru Outback 2.5i Limited 4 DR Wagon
4cyl Gasoline 2.5
Continuously Variable Tr

Lic Expire:
Veh Insp# :
Condition:
Ext. Color: Tungsten Metallic
Ext. Refinish: Two-Stage
Ext. Paint Code: TGM

VIN: 4S4BRBMC3E3300373
Mileage Type: Actual
Code: F2284A
Int. Color: Warm Ivory
Int. Refinish:
Int. Trim Code: WL80

Options

1st Row LCD Monitor(s)
Air Conditioning
Amplifier
Automatic Dimming Mirror
Bucket Seats
Daytime Running Lights
Dual Power Seats
Floor Mats
Halogen Headlights
Heated Front Seats

2nd Row Head Airbags
Alarm System
Anti-Lock Brakes
Bodyside Cladding
Center Console
Digital Signal Processor
Dual Zone Auto A/C
Fog Lights
Harman Kardon Sound Sys
Heated Power Mirrors

AM/FM CD Player
Aluminum/Alloy Wheels
Auto Headlamp Control
Bodyside Moldings
Cruise Control
Dual Airbags
Electronic Compass
Garage Door Opener
Head Airbags
Heated W/S Wiper Washers

High Definition Radio	Illuminated Visor Mirror	Intermittent Wipers
Keyless Entry System	Leather Seats	Leather Steering Wheel
Lighted Entry System	MP3 Decoder	Mud/Splash Guards
Navigation System	Overhead Console	Pelvic Airbags
Power Brakes	Power Door Locks	Power Moonroof
Power Steering	Power Windows	Pwr Driver Lumbar Supp
Rear Spoiler	Rear View Camera	Rear Window Defroster
Rear Window Wiper/Washer	Rem Trunk-L/Gate Release	Roof/Luggage Rack
Side Airbags	SiriusXM Satellite Radio	Split Folding Rear Seat
Stability Cntrl Suspensn	Strg Wheel Radio Control	Tachometer
Tilt & Telescopic Steer	Tinted Glass	Tire Pressure Monitor
Tonneau/Cargo Cover	Traction Control System	Trip Computer
USB Audio Input(s)	Wireless Audio Streaming	Wireless Phone Connect

Damages

Line	Op	Guide	MC	Description	MFR.Part No.	Price	ADJ% B%	Hours	R	
Rear Bumper										
1	N	574		RR Bumper Cvr Overhaul	Additional Labor			INC	SM	
2	EP	566		Cover,Rear Bumper	Replace PXN	\$261.00		2.3	SM	
				>> Keystone - Tulsa 888-892-6790						
				>> 9797 E Admiral Place						
				>> Tulsa OK 74116						
				>> APU Quote# 111778389450072, Stock# SU1100164PP LKQ# 3458679531						
3	L	566	13	Cover,Rear Bumper	Refinish			3.5	RF	
					2.4 Surface					
					0.6 Two-stage setup					
					0.5 Two-stage					
4	E	451		Pad,Rear Bumper Step	E771SAJ000	\$69.95		INC	SM	
Manual Entries										
5	SB	M03		Flex Additive	Sublet Repair	\$10.00*			RF*	
6	SB	M60		Hazardous Waste Removal	Sublet Repair	\$5.00*			SM*	
7	N			PRE-SCAN	Additional Labor			0.5*	ME*	
8	N			POST-SCAN	Additional Labor			0.5*	ME*	
8				Items						

MC Message

13 INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

Estimate Total & Entries

OEM Parts	\$69.95
Other Parts	\$261.00
Paint & Materials	3.5 Hours @ \$52.00 \$182.00
Parts & Material Total	\$512.95
Tax on Parts & Material	@ 8.517% \$43.69

Labor	Rate	Replace Hrs	Repair Hrs	Total Hrs	
Sheet Metal (SM)	\$70.00	2.3		2.3	\$161.00
Mech/Elec (ME)	\$125.00		1.0	1.0	\$125.00
Frame (FR)	\$100.00				
Refinish (RF)	\$70.00	3.5		3.5	\$245.00

Labor Total 6.8 Hours \$531.00

Sublet Repairs
Gross Total
Net Total

\$15.00

\$1,102.64
\$1,102.64 USD

ClaimID: 125E0BFD-9EAB-4CB1-8606-CEC844B17992
Alternate Parts Y/01/01/00/00/00 Cumulative 01/01/00/00/00 Zip Code: 74135 Default
Recycled Parts Y/0/0 Zip Code: 74135
Rate Name Default

Audatex Estimating 10.35.99 ES 05/12/2026 11:09 AM REL 10.35.99 DT 04/01/2026 DB 05/08/2026
State Disclosure:Not Selected
© 2026 Audatex North America, LLC.

1.1 HRS WERE ADDED TO THIS ESTIMATE BASED ON AUDATEX'S TWO-STAGE REFINISH FORMULA.

Op Codes

* = User-Entered Value	^ = Labor Matches System Assigned Rates	E = Replace OEM
NG = Replace NAGS	EC = Replace Economy	OE = Replace PXN OE Srpls
UE = Replace OE Surplus	ET = Partial Replace Labor	EP = Replace PXN
EU = Replace Recycled	TE = Partial Replace Price	PM = Replace PXN Reman/Reblt
UM = Replace Reman/Rebuilt	L = Refinish	PC = Replace PXN Reconditioned
UC = Replace Reconditioned	TT = Two-Tone	SB = Sublet Repair
N = Additional Labor	BR = Blend Refinish	I = Repair
IT = Partial Repair	CG = Chippguard	RI = R & I Assembly
P = Check	AA = Appearance Allowance	RP = Related Prior Damage



This report contains proprietary information of Audatex and may not be disclosed to any third party (other than the insured, claimant and others on a need to know basis in order to effectuate the claims process) without Audatex's prior written consent.

© 2026 Audatex North America, LLC.
AUDATEX is a trademark owned by Audatex North America, LLC. All rights reserved.



