


KEN DOKE
MUSKOGEE DISTRICT 1

KEITH HYSLOP
MUSKOGEE DISTRICT 2

KENNY PAYNE
MUSKOGEE DISTRICT 3



POLLY IRVING
COUNTY CLERK



SHEILA SHAMBLIN
SECRETARY

MUSKOGEE BOARD OF COUNTY COMMISSIONERS

P.O. BOX 2307 MUSKOGEE, OK 74402-2307 PHONE (918)682-9601 * FAX (918) 684-1697

RESOLUTION

Whereas: The Muskogee Board of County Commissioners met on the 30th day of January, 2023 to consider:

the use of the deductible fund to pay a claim in the amount of \$14,318.55 for damages to Muskogee Sheriff's Office 2021 Ford Police Interceptor 4D Ut, VIN#1FM5K8AB7MGA24867.

Whereas: a 2021 Ford Police Interceptor 4D Ut, VIN#1FM5K8AB7MGA24867, in the inventory of Muskogee Sheriff's Office was involved in an accident on 1/23/23.

and

Whereas: the vehicle is in need of repairs in the amount of \$14,318.55.


and


Whereas: ACCO has requested authorization from the Board of County Commissioners to use the Deductible Fund to pay the damage claim for said Muskogee Sheriff's Office 2021 Ford Police Interceptor, in the amount of \$14,318.55.


NOW, THEREFORE, BE IT RESOLVED;


The Muskogee Board of County Commissioners does hereby authorize ACCO-SIG to use the Deductible Fund to pay a claim for Muskogee Sheriff's Office, in the amount \$14,318.55, for damages to a 2021 Ford Police Interceptor 4D Ut, VIN#1FM5K8AB7MGA24867.


MUSKOGEE BOARD OF COUNTY COMMISSIONERS


ATTEST: POLLY IRVING
COUNTY CLERK




KENNY PAYNE
CHAIRMAN


KEN DOKE
MEMBER


KEITH HYSLOP
MEMBER

Date: 1/26/2023 09:39 AM
 Estimate ID: 23007
 Estimate Version: 0
 Profile ID: * Tulsa
 Quote ID: 118146383

GREEN COUNTRY APPRAISERS

TULSA, OK
 (918) 853-3144
 Fax: (918) 234-4045
 Email: greencountryapp@att.net

Damage Assessed By: Ron Myers

Appraised For: ANDY KELLER
 (405) 516-5324

Classification: Field

Condition Code: Average
 Date of Loss: 1/23/2023
 Contact Date: 1/25/2023
 Deductible: UNKNOWN
 File Number: 23007
 Claim Number: VAALAC075042

Type of Loss: Collision
 Arrival Date: 1/24/2023
 Accident Date: 1/23/2023

Insured: MUSKOGEE CTY SHERIFF
 Address: 220 STATE ST, MUSKOGEE, OK 74401
 Telephone: Work Phone: (918) 687-0202

Mitchell Service: 912181

Description: 2021 Ford Police Intrcpt Ut
 Body Style: 4D Ut
 VIN: 1FM5K8AB7MGA24867
 Mileage: 47,437
 OEM/ALT: O
 Color: BLACK/WHITE
 Options: PASSENGER AIRBAG, POWER DRIVER SEAT, POWER LOCK, POWER WINDOW, POWER STEERING
 POWER BRAKE, REAR WINDOW DEFOGGER, CRUISE CONTROL, TILT STEERING COLUMN
 FM RADIO, ANTI-LOCK BRAKE SYS., TIRE INFLATION/PRESSURE MONITOR

Drive Train: 3.3L Inj 6 Cyl AWD
 License: CO29707 OK

Search Code: None

!!!!!!NOTICE TO REPAIR FACILITY!!!!!!

NO SUPPLEMENTS WILL BE APPROVED WITHOUT PRIOR AUTHORIZATION BY APPRAISER AND/OR CLAIMS ADJUSTER. COPIESW OF ALL PARTS AND/OR SERVICE INVOICES USED IN REPAIR MUST BE SUBMITTED WITH SUPPLEMENT.

THIS APPRAISAL IS "NOT" AN AUTHORIZATION TO REPAIR OR GUARANTEE OF PAYMENT. AUTHORIZATION TO REPAIR CAN ONLY BE GIVEN BY OWNER OF MOTOR VEHICLE.

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
1	200579	BDY	REMOVE/INSTALL	Frt Bumper Cover			INC
2	200580	BDY	OVERHAUL	Frt Bumper Cover Assy			3.8
3	201457	BDY	REPAIR	Frt Upr Bumper Cover	Existing		1.0*
4	AUTO	REF	REFINISH	Frt Upr Bumper Cover			C 2.7
5	200536	BDY	REMOVE/REPLACE	R Fender Panel	LB5Z 16005 A	289.40	2.0 #
6	AUTO	REF	REFINISH	R Add To Edge Fender			C 0.5
7	AUTO	REF	REFINISH	R Fender Outside			C 2.0

ESTIMATE RECALL NUMBER: 01/26/2023 09:38:22 23007

Mitchell Data Version: OEM: DEC_22_V

Copyright (C) 1994 - 2022 Mitchell International
 All Rights Reserved

Software Version: 7.1.242

Page 1 of 4

Date: 1/26/2023 09:39 AM
 Estimate ID: 23007
 Estimate Version: 0
 Profile ID: * Tulsa
 Quote ID: 118146383

8	AUTO	BDY	REMOVE/INSTALL	R Front Combination Lamp				0.3	#
9	AUTO	BDY	REMOVE/INSTALL	R Cowl Top Grille				0.7	#
10	202151	BDY	REMOVE/REPLACE	R Fender Wheel Opening Mldg		LB5Z 16038 AA	306.57	INC	#
11	200274	MCH	REMOVE/REPLACE	Air Bag Restraint Control Module	-M	LB5Z 14B321 A	373.75	0.5	#
12	201117	MCH	REMOVE/REPLACE	Disable & Enable Air Bag System	-M				INC
13	201118	MCH	REMOVE/REPLACE	Air Bag System Diagnosis	-M			1.5	#
14	200165	MCH	REMOVE/REPLACE	R Air Bag Side Curtain Module	-M	LB5Z 78042D94 C	751.08	0.8	#
15	AUTO	BDY	REMOVE/INSTALL	Roof Headliner				5.4	#
16	200166	MCH	REMOVE/REPLACE	L Air Bag Side Curtain Module	-M	LB5Z 78042D95 C	751.08	0.8	#
17	200172	MCH	REMOVE/REPLACE	Air Bag Module-Passenger Seat	-M	MB5Z 78611D10 B	178.37	0.9	#
18	AUTO	BDY	REMOVE/INSTALL	R Frt Seat Assy				0.4	
19	200174	MCH	REMOVE/REPLACE	Air Bag Module-Drivers Seat	-M	MB5Z 78611D11 B	136.82	0.9	#
20	AUTO	BDY	REMOVE/INSTALL	L Frt Seat Assy				0.4	
21	200177	MCH	REMOVE/REPLACE	R Frt Air Bag Side Impact Sensor	-M	GN1Z 14B345 A	43.28	0.3	#
22	AUTO	BDY	REMOVE/INSTALL	R Frt Door Trim Panel					INC
23	200178	MCH	REMOVE/REPLACE	L Frt Air Bag Side Impact Sensor	-M	GN1Z 14B345 A	43.28	0.3	#
24	AUTO	BDY	REMOVE/INSTALL	L Frt Door Trim Panel					INC
25	200179	MCH	REMOVE/REPLACE	R Rear Air Bag Side Impact Sensor	-M	LT1Z 14B004 A		0.3	#
26	200180	MCH	REMOVE/REPLACE	L Rear Air Bag Side Impact Sensor	-M	LT1Z 14B004 A		0.3	#
27	201166	BDY	REPAIR	R Door Opening Panel		Existing		12.0	*#
28				R Center Post & R Rocker					
29	201235	BDY	REMOVE/REPLACE	R Frt Rocker Scuff Plate		LB5Z 7813208 DA	118.87	0.3	
30	931008	MCH	CHECK/ADJUST	Front/Rear Suspension		Sublet	99.95	* 0.0	*
31	201241	BDY	REMOVE/REPLACE	R Frt Door Opening Weatherstrip		LB5Z 7820708 A	135.38	INC	
32	201289	BDY	REMOVE/REPLACE	R Frt Seat Belt		LB5Z 78611B08 AA	344.82	0.4	#
33	201290	BDY	REMOVE/REPLACE	L Frt Seat Belt		LB5Z 78611B09 AA	308.20	0.4	#
34	201292	BDY	REMOVE/REPLACE	R Frt Seat Belt Height Adjuster		LB5Z 78602B82 A	35.70	0.2	#
35	201293	BDY	REMOVE/REPLACE	L Frt Seat Belt Height Adjuster		LB5Z 78602B82 A	35.70	0.2	#
36	201296	BDY	REMOVE/REPLACE	R Frt Seat Belt Buckle		LB5Z 7861202 AA	166.47	0.3	#
37	201291	BDY	REMOVE/REPLACE	L Frt Seat Belt Buckle		KS7Z 5461203 CA	120.92	0.3	#
38	201297	MCH	REMOVE/REPLACE	R Rear Seat Belt	-M	LB5Z 78611B68 AA	233.63	0.4	#
39	201298	MCH	REMOVE/REPLACE	L Rear Seat Belt	-M	LB5Z 78611B69 AA	231.18	0.4	#
40	201301	BDY	REMOVE/REPLACE	Rear Ctr Seat Belt		LB5Z 78611B64 CA	123.48	1.0	#
41	201311	BDY	REMOVE/REPLACE	R Rear Seat Belt Buckle		LB5Z 7860044 AA	73.13	0.3	#
42	AUTO	BDY	REMOVE/INSTALL	R Rear Seat Assy				0.4	
43	201312	BDY	REMOVE/REPLACE	L Rear Seat Belt Buckle		LB5Z 7860044 AA	73.13	0.3	#
44	AUTO	BDY	REMOVE/INSTALL	L Rear Seat Assy				0.4	
45	201313	BDY	REMOVE/REPLACE	Rear Ctr Seat Belt Buckle		LB5Z 7860045 AA	37.53	0.2	#
46	201299	BDY	REMOVE/REPLACE	R Frt Door Shell		NB5Z 7820124 B	1,125.70	5.7	#
47	AUTO	REF	REFINISH	R Frt Door Outside					C 1.9
48	AUTO	REF	REFINISH	R Frt Add For Jambs & Interior					C 1.0
49	200010	BDY	REMOVE/REPLACE	R Frt Door Sash Moulding		LB5Z 7820554 A	101.80	INC	#
50	200015	BDY	REMOVE/REPLACE	R Frt Lwr Door Moulding		LB5Z 7820878 AA	133.13	INC	
51	200913	GLS	REMOVE/REPLACE	R Frt Door Moveable Glass		LB5Z 7821410 A	319.30	INC	#
52	AUTO	BDY	REMOVE/INSTALL	R Frt Door Frame Mldg					INC #
53	AUTO	BDY	REMOVE/INSTALL	R Frt Door Carrier					INC #
54	200914	GLS	REMOVE/REPLACE	L Frt Door Moveable Glass		LB5Z 7821411 A	319.30	0.5	#
55	AUTO	BDY	REMOVE/INSTALL	L Frt Door Frame Mldg				0.2	#
56	AUTO	BDY	REMOVE/INSTALL	L Frt Door Carrier				1.0	#
57	931127	MCH	ADD'L LABOR OP	Pre Repair Scan		Existing		1.0	*
58	931128	MCH	ADD'L LABOR OP	Post Repair Scan		Existing		1.0	*
59	200927	BDY	REMOVE/REPLACE	R Rear Door Shell		LB5Z 7824630 B	899.17	5.6	#
60	AUTO	REF	REFINISH	R Rear Door Outside					C 1.9
61	AUTO	REF	REFINISH	R Rear Add For Jambs & Interior					C 1.0
62	200932	BDY	REMOVE/REPLACE	R Rear Door Front Sash Moulding		LB5Z 78255A34 A	102.30	INC	#
63	200938	BDY	REMOVE/REPLACE	R Rear Lwr Door Moulding		LB5Z 7825556 AA	134.87	INC	
64	936001		ADD'L COST	Towing			168.37	*	
65	936002		ADD'L COST	Storage			39.29	*	
66	933006	FRM	ADD'L OPR	Frame/Rack Set Up					2.0*
67	933035	FRM	ADD'L OPR	Unibody Pull					2.0*
68				R Door Opening					
69	933036	FRM	ADD'L OPR	Sheetmetal Pull					4.0*

ESTIMATE RECALL NUMBER: 01/26/2023 09:38:22 23007
 Mitchell Data Version: OEM: DEC_22_V

Date: 1/26/2023 09:39 AM
Estimate ID: 23007
Estimate Version: 0
Profile ID: * Tulsa
Quote ID: 118146383

Point(s) of Impact

3 Right Side (P), 2 Right Front Side (S)

Insurance Co: COUNTY CLAIMS OF OKLAHOMA
Address: 423 N.E. 50TH ST
OKLAHOMA CITY, OK 73105
Telephone: (877) 962-1920

Inspection Site: MORGAN'S TOWING
MUSKOGEE, OK
Inspection Date: 1/25/2023

Body Shop: MERRILL PAINT & BODY
Address: 4904 E 133 ST S
MUSKOGEE, OK 74403
Telephone: (918) 989-5417

GREEN COUNTRY APPRAISERS SPECIFIES AND INTENDS THAT ALL REPAIRS AND/OR PARTS REPLACEMENTS LISTED HEREON BE MADE IN STRICT ACCORDANCE WITH MANUFACTURERS RECOMMENDATIONS. PLEASE GIVE A COPY OF THIS APPRAISAL TO THE REPAIR FACILITY, BY NOT DOING SO COULD RESULT IN AN ADDITIONAL COST TO YOU. THIS APPRAISAL MAY HAVE BEEN CALCULATED USING A PRESET MAXIMUM ON PAINT/MATERIAL, CLEAR COAT AND/OR THREE STAGE. THIS APPRAISAL MAY HAVE BEEN PREPARED BASED ON THE USE OF ONE OR MORE REPLACEMENT PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER AND/OR THE DISTRIBUTOR OF THE REPLACEMENT PARTS RATHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE.

!!!!!!WARNING!!!!!!

ANY PERSON WHO KNOWINGLY AND WITH THE INTENT TO INJURE, DEFRAUD OR DECEIVE ANY INSURER AND WHO MAKES ANY CLAIM FOR THE PROCEEDS OF AN INSURANCE POLICY CONTAINING ANY FALSE, INCOMPLETE OR MISLEADING INFORMATION, IS GUILTY OF A FELONY.