


KEN DOKE
MUSKOGEE DISTRICT 1

KEITH HYSLOP
MUSKOGEE DISTRICT 2

KENNY PAYNE
MUSKOGEE DISTRICT 3



POLLY IRVING
COUNTY CLERK



SHEILA SHAMBLIN
SECRETARY

MUSKOGEE BOARD OF COUNTY COMMISSIONERS

P.O. BOX 2307 MUSKOGEE, OK 74402-2307 PHONE (918)682-9601 * FAX (918) 684-1697

RESOLUTION

Whereas: The Muskogee Board of County Commissioners met on the 5th day of June, 20 23 to consider:

the use of the deductible fund to pay a claim in the amount of \$5,635.71 for damages to Muskogee County District 2, 2008 Chevrolet Silverado C3500 Truck, VIN# 1GBJC33668F183043

Whereas: a 2008 Chevrolet Silverado C3500 Truck, VIN# 1GBJC33668F183043, in the inventory of Muskogee County District 2 was involved in an accident on 5/22/23.

and

Whereas: the 2008 Chevrolet Silverado C3500 Truck is in need of repair in an amount of \$5,635.71.


and


Whereas: ACCO has requested authorization from the Board of County Commissioners to use the Deductible Fund to pay the damage claim for said Muskogee County District 2 2008 Chevrolet Silverado C3500 Truck, in an amount of \$5,635.71.

NOW, THEREFORE, BE IT RESOLVED;

The Muskogee Board of County Commissioners does hereby authorize ACCO-SIG to use the Deductible Fund to pay a claim for Muskogee County District 2, in an amount of \$5,635.71, for a repair total of a 2008 Chevrolet Silverado C3500 Truck, VIN# 1GBJC33668F183043.

MUSKOGEE BOARD OF COUNTY COMMISSIONERS


ATTEST: POLLY IRVING
COUNTY CLERK




KENNY PAYNE, CHAIRMAN


KEN DOKE, MEMBER


KEITH HYSLOP, MEMBER



Invoice #: T1054187 - Final
Date of Bill: 05/30/2023
Remit To: Frontier Adjusters Inc.
P.O. Box 650950
Dallas, TX 75265-0950
IRS NO. 84-0484390

ACCO
429 NE 50th Street
Oklahoma City, OK 73105
United States

ATTENTION: Carson Bunce
carsonb@okacco.com

OFFICE:	N20 - Muskogee	LOSS DT:	05/22/2023
OUR FILE #:	MF23-0831	RECEIVED DT:	05/22/2023
YOUR CLAIM #:	VAAP075413	INSURED:	Danny Taylor
ADJUSTER:	Wesley Bolin	CLAIMANT:	
POLICY #:			

ADJUSTING SERVICES

Adjusting Services \$236.00 USD

EXPENSE SERVICES

Gas Surcharge (Retail \$3.00 - \$3.50/gallon) \$5.00 USD
Miles/Kilometers (Standard) \$6.75 USD
Photos (10 included) \$26.00 USD

Total Adjusting Services: \$236.00 USD
Total Expenses: \$37.75 USD
Subtotal: \$273.75 USD

Office Overhead: \$0.00 USD
Sales Tax: \$0.00 USD

Total Bill: \$273.75 USD

Please remit copy with payment. We appreciate your payment within 30 days.



Timesheet Detail

Invoice #: T1054187

Our File #: MF23-0831

Company: ACCO

Company Claim #: VAAP075413

Invoice Date: 05/30/2023

POLICY #:

DATE	IA	ADJ ACTIVITY OR EXPENSE	QTY UNIT	AMT	TOTAL
05/25/2023	Bolin, Wesley	<u>Miles/Kilometers (Standard)</u>	9.00 Mile	\$0.75	\$6.75
		Mileage to inspection location near Martin, Ok. and return to office in Muskogee, Ok. 29 miles less 20 included.			
	Bolin, Wesley	<u>Adjuster Hours</u>	0.80 Hour	\$95.00	\$76.00
		Drive time to inspection location near Martin, Ok. and return to office in Muskogee, Ok.			
	Bolin, Wesley	<u>Gas Surcharge (Retail \$3.00 - \$3.50/gallon)</u>	1.00 Each	\$5.00	\$5.00
		Fuel Surcharge.			
05/29/2023	Bolin, Wesley	<u>Auto Appraisal - \$0.00 - \$30,000.00</u>	1.00 Fee	\$160.00	\$160.00
		Auto Appraisal for Insured Vehicle			
	Bolin, Wesley	<u>Photos (10 included)</u>	26.00 Each	\$1.00	\$26.00
		36 photos total minus 10 included = 26 photos			

SUMMARY:	
Adjusting Hours	1.80
Adjusting Services	\$236.00 USD
Expenses	\$37.75 USD
Subtotal	\$273.75 USD
Sales Tax	\$0.00 USD
Total Amount	\$273.75 USD



PO Box 1195 | 866.364.0185 Phone
Ardmore, OK 73401 | 800.327.3424 Fax
wbolin@frontieradjusters.com | 580.927.0194 Cell

May 29, 2023

ACCO
Carson Bunce
429 NE 50th St
Oklahoma City, OK 73105
carsonb@okacco.com

Re: Named Insured: Muskogee County Dist. #2
 Company Claim #: VAAP075413
 Type of Loss: Auto Appraisal
 Date of Loss: May 22, 2023
 Loss Location: S 85th St Warner, OK
 Frontier File #: MF23-0831
 Claimant(s):

APPRAISAL REPORT

Assignment/Contact:

This assignment was received on 5/22/2023. The inspection was set up for and completed on 5/25/2023 @ 6:30 p.m. at the residence of Danny Taylor near Warner, OK. The assignment was to obtain photos of the vehicle and prepare an estimate of the damages. I was met by Danny, an employee of the district, upon arrival for the inspection.

Insured:

Muskogee County
Keith Hyslope / Danny Taylor
918-577-2028 / 918-577-1077

Vehicle:

2008 Chevy 3500 Diesel, 4D, DRW
VIN: 1GBJC33668F183043
Mileage: 269,749

Loss:

The vehicle was reported to have been involved in a deer strike on the morning of May 22, 2023 by Danny Taylor, an employee of the county. I contacted Danny on May 23, 2023 to set up a time for the inspection at his residence for the evening of May 25, 2023.

The vehicle is equipped with a grill guard which absorbed most of the damage and possibly saved the coolers from being damaged as well as the deployment of the airbags. The vehicle sustained damage to the right fender, right headlight, hood, windshield, and front bumper.

The grill guard, hood, fender, headlight, windshield, and bumper components will need to be replaced. Hidden damage may be discovered once the vehicle is tore down for repairs that was not visible upon the initial inspection.

The vehicle is repairable and an estimate in the amount of \$5,635.71 has been prepared for submittal to your office. The national average for this vehicle depending on mileage, options, and condition is \$13,000 to \$16,000.

I spoke with the clerk on May 26, 2023 and she stated that they would get 3 quotes for repairs but did not know at that time where they would have the repairs completed.

Future Activities:

As all requested activity has been completed, we are closing our file at this time and submitting our service invoice for your consideration. Thank you for allowing us to assist on this assignment.

Enclosures:

Estimate
Photo Sheet
Service Invoice

Prepared by,

Wesley Bolin
(580)927-0194
Frontier Adjusters of Muskogee
wbolin@frontieradjusters.com

Frontier Adjusters of Muskogee, OK
P.O. Box 471006
Tulsa, OK. 74147
Office: (877) 628-1714
Fax: (888) 743-1543 / Cell: (580) 927-0194

*** ESTIMATE ***

05/28/2023 10:03 AM

Owner

Owner: Muskogee County Dist. #2
Contact: Keith Hyslope
Address: 306 W Zenith Warner
City State Zip: Muskogee, OK 74403
Work/Day: (918)577-2028
FAX:

Control Information

Claim # : VAAP075413
Loss Date/Time: 05/22/2023
Deductible: Unknown
File # : MF23-0831
Insured Policy # :
Loss Type: Comprehensive
Accounting # :

Ins. Company: ACCO
Company Contact: Carson Bunce
Address: 429 NE 50th Street
City State Zip: Oklahoma City, OK 73105
Email: carsonb@okacco.com
Work/Day: (405)516-5324
FAX:

Insured: Muskogee Co. Dist. #2
Contact: Keith Hyslope
Address: 306 W Zenith Warner
City State Zip: Muskogee, OK 74403
Work/Day: (918)577-2028
FAX:

Claim Rep: ACCO
Contact: Carson Bunce
Address: 429 NE 50th Street
City State Zip: Oklahoma City, OK 73105
Email: carsonb@okacco.com
Work/Day: (405)516-5324
FAX:

Inspection

Inspection Date: 05/25/2023 06:15 PM
Inspection Location: 8264 E 125th St S
Address: 8264 E 125th St S
City State Zip: Muskogee, OK 74403
Primary Impact: Front
Driveable: Yes
Inspection Type: Independent Field
Contact: Danny Taylor
Work/Day: (918)577-1077
FAX:
Secondary Impact:
Rental Assisted:

Company: Frontier Adjusters
Contact: Wesley Bolin
Address: P.O. Box 1195
City State Zip: Ardmore, OK 73402
Email: wbolin@frontieradjusters.com
Appraiser License # : 3001357877
Work/Day: (580)927-0194
FAX: (800)327-3424

Repairer

Target Complete Date/Time:

Days To Repair: 9

Vehicle

OEM Part Price Quote ID: 124067600

2008 Chevrolet Silverado C3500 Work Truck 4 DR Crew Cab Long Bed
 8cyl Diesel Turbo 6.6
 6-Speed Automatic

Lic.Plate: 16334
Lic Expire:
Prod Date: 01/2008
Veh Insp# :
Condition: Fair
Ext. Color: OLYMPIC WHITE
Ext. Refinish: Two-Stage
Ext. Paint Code: 50,8624

Lic State: OK
VIN: 1GBJC33668F183043
Mileage: 269,749
Mileage Type: Actual
Code: U8766G
Int. Color:
Int. Refinish: Two-Stage
Int. Trim Code:

Options

AM/FM Stereo	Air Conditioning	Anti-Lock Brakes
Clearance Lights	Dual Airbags	Dual Zone Auto A/C
Fender Flares	Heavy Duty Suspension	Intermittent Wipers
Limited Slip Differential	Power Brakes	Power Steering
Rear Bench Seat	Rear Step Bumper	Split Front Bench Seat
Tachometer	Tilt Steering Wheel	Tinted Glass
Vinyl Seats		

Damages

Line	Op	Guide	MC	Description	MFR.Part No.	Price	ADJ%	B%	Hours	R
Front Bumper										
1	EP	24		Bumper,Front	Replace PXN	\$254.00			INC	SM
2	N	8		Front Bumper Overhaul	Additional Labor				4.2	SM
3	EP	142		Cover,Front Bumper LT	Replace PXN	\$222.30			INC	SM
4	EP	143		Cover,Front Bumper RT	Replace PXN	\$200.00			INC	SM
5	EP	152		Defl,Front Bumper	Replace PXN	\$95.00			INC	SM
Front End Panel And Lamps										
6	EP	300		Grille Assembly	Replace PXN	\$350.00			INC	SM
7		1003		Clip,Grille	Replace OEM	INC				SM
				Quantity of 6 @ INC each						SM
8	EP	42		Headlamp Assy,Halogen RT	Replace PXN	\$137.00			0.3	SM
9	N	973		Headlamps Aim	Additional Labor				0.4	SM
10	EP	122		Brkt,Headlamp Mtg LT	Replace PXN	\$20.00			0.3	SM
Radiator Support										
11	EP	455		Brkt,Headlamp Mtg RT	Replace PXN	\$35.00			0.1	SM
Front Body And Windshield										
12	EP	83		Panel,Hood	Replace PXN	\$320.00			1.6	SM
13	L	83	13	Panel,Hood	Refinish				6.3	RF
14	EP	197		Mldg,Hood Front	Replace PXN	\$89.00			INC	SM
15	RI	136		Mldg,Hood Rear LT	R & I Assembly				INC	SM
16	RI	137		Mldg,Hood Rear RT	R & I Assembly				INC	SM
17	RI	88		Latch,Hood Panel	R & I Assembly				INC	SM
18	EP	453		Bracket,Hood Catch	Replace PXN	\$59.00			0.6	SM

19	RI	86	Pad,Insulator Hood	R & I Assembly			0.5	SM
20	BR	103	Fender,Front LT	Blend Refinish			1.4	RF
21	EP	104	Fender,Front RT	Replace PXN	\$299.00		2.8	SM
22	L	104	Fender,Front RT	Refinish			4.0	RF
23	NG	59	Windshield,Shaded	NAGS DW1658-GT	\$255.48		2.0	SM

Front Body Interior Sheetmetal

24	EP	109	Shield,Front Splash RT	Replace PXN	\$25.00		INC	SM
----	----	-----	------------------------	-------------	---------	--	-----	----

Front Suspension

25	N	974	Suspension Align,Frt	Additional Labor			1.5	ME
----	---	-----	----------------------	------------------	--	--	-----	----

Manual Entries

26	SB	M14	Corrosion Protection	Sublet Repair	\$10.00*			RF
27	SB	M17	Cover Car Exterior	Sublet Repair			0.2*	RF
28	SB	M60	Hazardous Waste Removal	Sublet Repair	\$5.00*			SM
29	EC		Grill Guard	Replace Economy	\$912.74*	+25.00	1.5*	SM*
			>> Ranch Hand Grill Guard					

29 Items

MC Message

13 INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

Estimate Total & Entries

Other Parts		\$3,273.52	
Paint & Materials	11.9 Hours @ \$45.00	\$535.50	
Line Item Markup		\$228.19	
Parts & Material Total			\$4,037.21

Labor	Rate	Replace Hrs	Repair Hrs	Total Hrs	
Sheet Metal (SM)	\$55.00	9.7	4.6	14.3	\$786.50
Mech/Elec (ME)	\$95.00		1.5	1.5	\$142.50
Frame (FR)	\$55.00				
Refinish (RF)	\$55.00	11.7	0.2	11.9	\$654.50

Labor Total	27.7 Hours	\$1,583.50
Sublet Repairs		\$15.00
Gross Total		\$5,635.71
Less: Deductible		Unknown-
Net Total		\$5,635.71

Alternate Parts Y/14/13/00/01/01 Cumulative 14/13/00/01/01 Zip Code: 73402 Geo 73402
 OEM Part Prices DT 05/28/2023 10:04 AM EstimateID 1092102248458100736 QuoteID 124067600
 SPPL Yes Zip Code: 00000 Default
 Rate Name Default

Audatex Estimating 10.21.138 ES 05/29/2023 01:18 PM REL 10.21.138 DT 05/01/2023 DB 05/15/2023
 State Disclosure:OK
 © 2023 Audatex North America, Inc.

2.8 HRS WERE ADDED TO THIS ESTIMATE BASED ON AUDATEX'S TWO-STAGE REFINISH FORMULA.

NOTICE: THIS IS A REPAIR ESTIMATE ONLY. THE INSURANCE POLICY MAY CONTAIN PROVISIONS THAT WILL REDUCE ANY PAYMENTS THAT MIGHT BE MADE. THIS IS NOT AN AUTHORIZATION TO REPAIR. AUTHORIZATION TO REPAIR OR GUARANTEE OF PAYMENT MUST COME FROM THE OWNER OF THE PROPERTY. ANY SUPPLEMENTS MUST BE APPROVED BY AN AUTHORIZED REPRESENTATIVE OR IT WILL NOT BE HONORED. NO ADJUSTER OR APPRAISER HAS THE AUTHORITY TO AUTHORIZE OR GUARANTEE PAYMENT. THE INSURER ASSUMES NO RESPONSIBILITY FOR THE QUALITY OF REPAIRS THAT MIGHT BE MADE.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF CRASH PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THESE PARTS RATHER THAN THE MANUFACTURER OF YOUR VEHICLE.

WARNING: ANY PERSON WHO KNOWINGLY, AND WITH INTENT TO INJURE, DEFRAUD OR DECEIVE ANY INSURER, MAKES ANY CLAIM FOR THE PROCEEDS OF AN INSURANCE POLICY CONTAINING ANY FALSE, INCOMPLETE OR MISLEADING INFORMATION IS GUILTY OF A FELONY.

Op Codes

* = User-Entered Value	^ = Labor Matches System Assigned Rates	E = Replace OEM
NG = Replace NAGS	EC = Replace Economy	OE = Replace PXN OE Srpls
UE = Replace OE Surplus	ET = Partial Replace Labor	EP = Replace PXN
EU = Replace Recycled	TE = Partial Replace Price	PM = Replace PXN Reman/Reblt
UM = Replace Reman/Rebuilt	L = Refinish	PC = Replace PXN Reconditioned
UC = Replace Reconditioned	TT = Two-Tone	SB = Sublet Repair
N = Additional Labor	BR = Blend Refinish	I = Repair
IT = Partial Repair	CG = Chipguard	RI = R & I Assembly
P = Check	AA = Appearance Allowance	RP = Related Prior Damage



This report contains proprietary information of Audatex and may not be disclosed to any third party (other than the insured, claimant and others on a need to know basis in order to effectuate the claims process) without Audatex's prior written consent.

© 2023 Audatex North America, Inc.
AUDATEX is a trademark owned by Audatex North America, Inc. All rights reserved.

"A trusted extension of your claims organization"

Claim #: VAAP075413

DOL: May 22, 2023

Claimant:

Insured: Danny Taylor



Photo #: 1

Date Taken:
05/25/2023

Taken By:
Wesley Bolin

Description:
Right Front Corner View



Photo #: 2

Date Taken:
05/25/2023

Taken By:
Wesley Bolin

Description:
Overview of Right Side

"A trusted extension of your claims organization"

Claim #: VAAP075413

DOL: May 22, 2023

Claimant:

Insured: Danny Taylor



Photo #: 3

Date Taken:

05/25/2023

Taken By:

Wesley Bolin

Description:

Hood Cowl & Badge




Photo #: 4

Date Taken:

05/25/2023

Taken By:

Wesley Bolin

Description:

Door Badge

"A trusted extension of your claims organization"

Claim #: VAAP075413

DOL: May 22, 2023

Claimant:

Insured: Danny Taylor



Photo #: 5

Date Taken:
05/25/2023

Taken By:
Wesley Bolin

Description:
County Vehicle ID



Photo #: 6

Date Taken:
05/25/2023

Taken By:
Wesley Bolin

Description:
Overview of Right Side

"A trusted extension of your claims organization"

Claim #: VAAP075413

DOL: May 22, 2023

Claimant:

Insured: Danny Taylor



Photo #: 7

Date Taken:
05/25/2023

Taken By:
Wesley Bolin

Description:
Right Rear Corner View



Photo #: 8

Date Taken:
05/25/2023

Taken By:
Wesley Bolin

Description:
Rear Overview

Click images for full-resolution

"A trusted extension of your claims organization"

Claim #: VAAP075413

DOL: May 22, 2023

Claimant:

Insured: Danny Taylor



Photo #: 9

Date Taken:

05/25/2023

Taken By:

Wesley Bolin

Description:

License Plate



Photo #: 10

Date Taken:

05/25/2023

Taken By:

Wesley Bolin

Description:

Left Rear Corner View

"A trusted extension of your claims organization"

Claim #: VAAP075413

DOL: May 22, 2023

Claimant:

Insured: Danny Taylor



Photo #: 11

Date Taken:
05/25/2023

Taken By:
Wesley Bolin

Description:
Overview of Left Side



Photo #: 12

Date Taken:
05/25/2023

Taken By:
Wesley Bolin

Description:
Overview of Left Side

"A trusted extension of your claims organization"

Claim #: VAAP075413

DOL: May 22, 2023

Claimant:

Insured: Danny Taylor



Photo #: 13

Date Taken:
05/25/2023

Taken By:
Wesley Bolin

Description:
Front Left Corner View



Photo #: 14

Date Taken:
05/25/2023

Taken By:
Wesley Bolin

Description:
Front Overview

"A trusted extension of your claims organization"

Claim #: VAAP075413

DOL: May 22, 2023

Claimant:

Insured: Danny Taylor



Photo #: 15

Date Taken:
05/25/2023

Taken By:
Wesley Bolin

Description:
Damaged Grill Guard



Photo #: 16

Date Taken:
05/25/2023

Taken By:
Wesley Bolin

Description:
Damaged Grill Guard



"A trusted extension of your claims organization"

Claim #: VAAP075413

DOL: May 22, 2023

Claimant:

Insured: Danny Taylor

	<p>Photo #: 17</p> <p>Date Taken: 05/25/2023</p> <p>Taken By: Wesley Bolin</p> <p>Description: Damaged Hood</p>
	<p>Photo #: 18</p> <p>Date Taken: 05/25/2023</p> <p>Taken By: Wesley Bolin</p> <p>Description: Damaged Hood</p>

[Click images for full-resolution](#)

"A trusted extension of your claims organization"

Claim #: VAAP075413

DOL: May 22, 2023

Claimant:

Insured: Danny Taylor



Photo #: 19

Date Taken:
05/25/2023

Taken By:
Wesley Bolin

Description:
Damaged Right Headlight



Photo #: 20

Date Taken:
05/25/2023

Taken By:
Wesley Bolin

Description:
Damaged Right Fender

"A trusted extension of your claims organization"

Claim #: VAAP075413

DOL: May 22, 2023

Claimant:

Insured: Danny Taylor



Photo #: 21

Date Taken:

05/25/2023

Taken By:

Wesley Bolin

Description:

Damaged Right Fender




Photo #: 22

Date Taken:

05/25/2023

Taken By:

Wesley Bolin

Description:

Damaged Right Fender

"A trusted extension of your claims organization"

Claim #: VAAP075413

DOL: May 22, 2023

Claimant:

Insured: Danny Taylor



Photo #: 23

Date Taken:

05/25/2023

Taken By:

Wesley Bolin

Description:

Damaged Right Fender Liner



Photo #: 24

Date Taken:

05/25/2023

Taken By:

Wesley Bolin

Description:

Damaged Right Side Bumper Cover

"A trusted extension of your claims organization"

Claim #: VAAP075413

DOL: May 22, 2023

Claimant:

Insured: Danny Taylor



Photo #: 25

Date Taken:
05/25/2023

Taken By:
Wesley Bolin

Description:
Damaged Bumper Deflector



Photo #: 26

Date Taken:
05/25/2023

Taken By:
Wesley Bolin

Description:
Steering Wheel w/ Options

"A trusted extension of your claims organization"

Claim #: VAAP075413

DOL: May 22, 2023

Claimant:

Insured: Danny Taylor



Photo #: 27

Date Taken:

05/25/2023

Taken By:

Wesley Bolin

Description:

Odometer (269,749)



Photo #: 28

Date Taken:

05/25/2023

Taken By:

Wesley Bolin

Description:

Radio & Climate Control Options

"A trusted extension of your claims organization"

Claim #: VAAP075413

DOL: May 22, 2023

Claimant:

Insured: Danny Taylor



Photo #: 29

Date Taken:

05/25/2023

Taken By:

Wesley Bolin

Description:

Driver Interior Overview



Photo #: 30

Date Taken:

05/25/2023

Taken By:

Wesley Bolin

Description:

Front Passenger Interior Overview

"A trusted extension of your claims organization"

Claim #: VAAP075413

DOL: May 22, 2023

Claimant:

Insured: Danny Taylor



Photo #: 31

Date Taken:

05/25/2023

Taken By:

Wesley Bolin

Description:

Cracked Windshield



Photo #: 32

Date Taken:

05/25/2023

Taken By:

Wesley Bolin

Description:

Damaged Hood Catch Bracket

"A trusted extension of your claims organization"

Claim #: VAAP075413

DOL: May 22, 2023

Claimant:

Insured: Danny Taylor




Photo #: 33

Date Taken:

05/25/2023

Taken By:

Wesley Bolin

Description:

Damaged Cooling Bracket



Photo #: 34

Date Taken:

05/25/2023

Taken By:

Wesley Bolin

Description:

Door VIN Decal



"A trusted extension of your claims organization"

Claim #: VAAP075413

DOL: May 22, 2023

Claimant:

Insured: Danny Taylor

	<p>Photo #: 35</p> <p>Date Taken: 05/25/2023</p> <p>Taken By: Wesley Bolin</p> <p>Description: MFG Date (01/2008)</p>
	<p>Photo #: 36</p> <p>Date Taken: 05/25/2023</p> <p>Taken By: Wesley Bolin</p> <p>Description: Paint Code</p>